

Fig. 1




Fig. 2




Fig. 3

REPLACEMENT SHEET 4 of 19

Synchronized with Falling Edge of Clock







Fig. 4



၅၀



6
Eig.




Fig. 7




Fig. 8





Fig. 9






Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16

Without DLL




Fig. 17A

With DLL




Fig. 17B




Fig. 18




Fig. 19